

16 Passingtabel inwendige maten

C : Voor inwendige maten volgens ISO 286 deel 2.

nominale maat

boven	:	3	6	10	18	30	50	80	120
tot en met	:	3	6	10	18	30	50	80	120
passing		tolerantievelen in 0,001 mm (μm)							

C13	+200	+240							
	+60	+60							
C14	+310	+370							
	+60	+70							
D9	+45	+60							
	+20	+30							
D10	+60	+78							
	+20	+30							
D11	+80	+115	+130						
	+20	+30	+40						
D12	+120	+150	+190	+230	+275	+330	+400	+470	+545
	+20	+30	+40	+50	+65	+80	+100	+120	+145
EF8	+24	+28	+40						
	+10	+14	+18						
E11	+74	+95	+115	+142					
	+14	+20	+25	+32					
E12	+100	+140	+175	+212					
	+14	+20	+25	+32					

F7	+16 +6	+22 +10	+28 +13	+34 +16	+41 +20	+50 +25	+60 +30	+71 +36	+83 +43
H5	+4 0	+5 0	+6 0	+8 0	+9 0	+11 0	+13 0	+15 0	+18 0
H7	+10 0	+12 0	+15 0	+18 0	+21 0	+25 0	+30 0	+35 0	+40 0
H8	+14 0	+18 0	+22 0	+27 0	+33 0	+39 0	+46 0	+54 0	+63 0
H9	+25 0	+30 0	+36 0	+43 0	+52 0	+62 0	+74 0	+87 0	+100 0
H11	+60 0	+75 0	+90 0	+110 0	+130 0	+160 0	+190 0	+220 0	+250 0
H12	+100 0	+120 0	+150 0	+180 0	+210 0	+250 0	+300 0	+350 0	+400 0
H13	+140 0	+180 0	+220 0	+270 0	+330 0	+390 0	+460 0	+540 0	+630 0
H14	+250 0	+300 0	+360 0	+430 0	+520 0	+620 0	+740 0	+870 0	+1000 0
H15	+400 0	+480 0	+580 0	+700 0	+840 0	+1000 0	+1200 0	+1400 0	+1600 0
JS9	+12,5 -12,5	+15 -15	+18 -18						
K9	0 -25	0 -30	0 -36						